MATERIAL SAFETY DATA SHEET JAN 29 1982 FOR COATINGS, RESINS AND RELATED MATERIALS DAM 2965 Series FEB 1216 1998 (Approved by U.S. Department of Labor "Essentially Similar" to Form OSHA-20) Resin, Del-Coat DATE OF PREP. 5/10/79 CA7096001 Section I Ram Chemicals Division - Whittaker Corporation MANUFACTURER'S NAME CITY, STATE, AND ZIP CODE Gardena, CA 90248 210 E. Alondra Blvd. STREET ADDRESS (213) 321-0710 EMERGENCY TELEPHONE NO. Polyester Gel Coats MANUFACTURERS CODE IDENTIFICATION RODUCT CLASS Ram Gel Coat **TRADE NAME** Section II — HAZARDOUS INGREDIENTS VAPOR PERCENT LEL NGREDIENT PRESSURE PPM mo/m³ 100 1.1 5 mm 35 - 38Styrene monomer Ηg

Section III - PHYSICAL DATA

293°F OILING RANGE

VAPOR DENSITY

X HEAVIER,

LIGHTER, THAN AIR

VAPORATION RATE

FASTER

SLOWER, THAN ETHER

PERCENT VOLATILE BY VOLUME

WEIGHT PER 10

10-12 lbs.

Section IV - FIRE AND EXPLOSION HAZARD DATA

STICATEGORY Flammable liquid, Red Label

FLASH POINT

88°-92°F (closed cup)

LEL 1.1

KTINGUISHING MEDIA Dry chemical, CO2, foam

NUSUAL FIRE AND EXPLOSION HAZARDS

Heat exposure may cause pressure build-up in closed containers; cool down with water.

JUL FIRE FIGHTING PROCEDURES

Fire fighting procedures are similar to those involved with aromatic hydrocarbons such as toluene.

Section V — HEALTH HAZARD C TA
THRESHOLD LIMIT VALUE 100 ppm EFFECTS OF OVEREXPOSURE Irritation of eyes, nose and throat; possible narcosis at high concentrations.
aliana di Kabupatèn Bandaran Kabupatèn Bandaran Kabupatèn Bandaran Kabupatèn Bandaran Kabupatèn Bandaran Kabup Kabupatèn Bandaran Kabupatèn Bandaran Kabupatèn Bandaran Kabupatèn Bandaran Kabupatèn Bandaran Kabupatèn Banda
EMERGENCY AND FIRST AID PROCEDURES Remove to fresh air; consult physician. For eye conta flush well with clear water for 15 minutes; consult physician.
Section VI — REACTIVITY DATA
STABILITY UNSTABLE X STABLE CONDITIONS TO AVOID INCOMPATABILITY (Materials to avoid) HAZARDOUS DECOMPOSITION PRODUCTS HAZARDOUS POLYMERIZATION X MAY OCCUR WILL NOT OCCUR CONDITIONS TO AVOID Catalyzation of large masses may allow build-up of exothermic heat
Section VII — SPILL OR LEAK PROCEDURES
steps to be taken in case material is released or spilled Remove sources of heat or flame; avoid prolonged breathing of vapors. Absorb spill with inert material and discar wasted is posal method. Follow normal practices for disposal of flammable liquids.
Section VIII — SPECIAL PROTECTION INFORMATION
RESPIRATORY PROTECTION Organic vapor respirators are recommended if the TLV must be exceeded.
VENTILATION Sufficient to maintain vapors below TLV.
PROTECTIVE GLOVES EYE PROTECTION Goggles may be desired for protection against spray or splashes. OTHER PROTECTIVE EQUIPMENT
Section IX — SPECIAL PRECAUTIONS
PRECAUTIONS TO BE TAKEN IN HANDLING AND STORING Store in closed containers well away from heat sources, sparks and open flame.
OTHER PRECAUTIONS Do not take internally. Keep out of reach of children. Avoid prolonged skin contact and breathing of vapors. Ground container when pouring to prevent generation of static charge.